Video System	Mapping	Problem
--------------	---------	---------

AFFECTED: SD1m, SD4m, SD4mX As well as their Reseller Designation versions

Please note: Unlike some other solutions providers who hide their flaws and hardware/software issues, we prefer to operate in an honest open manor that respects a customers right to know what they are getting and any problems & solutions

FIELD SERVICE MEMO #20 Issue Date January 11, 2014

American Bus Video 2545 Valley Ridge Dr. Cumming, GA. 30040 770-263-8118 Tel 770-887-5944 Fax

www.AmericanBusVideo.com

Торіс	Video System Mapping Problem	
Problem	Customers have noticed map display problems with the AVPlayer software	
Customer	SD4mX customers contacted ABV on 1-10-2014 reporting they had noticed;	
Complaint	the Google pointer on their AVPlayer software mapping tile was missing,	
Google	the map was moving erratically, followed by program freezing Google is the map program of choice for many mobile DVR software products. When Google	
Mapping	makes changes in their mapping program, that improve their product function on occasion	
Changes	this adversely affects those mobile video software programs using the product.	
	It is possible a couple new features recently added to the Google program	
	Map - <u>Terrain check box</u> added to enable or disable	
	Satellite -Labels check box added to enable or disable	
Manufacturer Notice	On 1-10-2014 we made the manufacturer aware of the problem. We tested several other	
Manufacturer	manufacturer products that also demonstrated the same problem. Within 12 hours of the reported problem, ABV received a corrected CMS software program,	
Action Taken	that was tested and mapping function verified to properly function.	
Customers	At this time we are recommending all customers of the above listed "Affected" products	
Recommended	Uninstall & Delete the ViewPro, AVPlayer & CMS Software currently on your PC.	
	Update the AVPlayer & CMS Software to	
	"2014.1.11 V2.35 G-Sens Mosaic"	
	New AVPlayer & CMS Software available for free download at:	
	http://www.americanbusvideo.com/CUSTOMER-	
	FTP/SD4mX/Video%20Player/Video%20Player%20V2.35%20G-Sens%20Mosaic/	
	Direct Link Download if supported by your browser:	
	MDR_Client_V2.35_EN(2).exe	
	MDR_Client_V2.35_EN(2).exe.zip	
	It is recommended that this process be completed ASAP to insure proper function of all software features	
Advice To New Users	New customers can simply download the latest software program online	